

0700415604

Case 41

1. STATE *Md*
 COUNTY *Carroll*
 TOWN
 STREET NO.
 VICINITY *Gambler*
 ORIGINAL OWNER
 ORIGINAL USE *dwelling*
 PRESENT OWNER
 PRESENT USE *dwelling* *Patterson*
 WALL CONSTRUCTION
 NO. OF STORIES

HISTORIC AMERICAN BUILDINGS SURVEY
INVENTORY

2. NAME *Patterson Farm*
 DATE OR PERIOD
 STYLE
 ARCHITECT
 BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC

*a late 19th. century farmhouse of
 no particular merit at this time*

5. PHYSICAL CONDITION OF STRUCTURE

Endangered

Interior

Exterior



6. LOCATION MAP (Plan Optional)

8. PUBLISHED SOURCES (Author, Title, Pages)
 INTERVIEWS, RECORDS, PHOTOS, ETC.

*Records - CARP H. Soc.,
 Westminster*

7. PHOTOGRAPH

9. NAME, ADDRESS AND TITLE OF RECORDER

JR Rivoire

MHT 12/70

DATE OF RECORD

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE

4.29

1. STATE

COUNTY *Carroll*

TOWN

VICINITY

STREET NO. *W. side of Louisville RD, N*
of junction of Louisville RD & Ind. 32 &

ORIGINAL OWNER *Boellinger mill RD.*

ORIGINAL USE

PRESENT OWNER *Marshall & Margaret Patterson*

PRESENT USE

WALL CONSTRUCTION

NO. OF STORIES

HISTORIC AMERICAN BUILDINGS SURVEY
INVENTORY

CARR-41

2. NAME *PATTERSON FARM*

DATE OR PERIOD

STYLE

ARCHITECT

BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC



Pleasant example of an early two story white farmhouse in this community.

log house - oldest part - on E end of house -

5. PHYSICAL CONDITION OF STRUCTURE *Endangered*

Interior

Exterior



6. LOCATION MAP (Plan Optional)

8. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.

Records - Carroll C.H. [unclear]

7. PHOTOGRAPH

9. NAME, ADDRESS AND TITLE OF RECORDER

D. Parish

DATE OF RECORD

1969